

- posunut prednu dierku na spodnej casti o 0.1mm
- niektore (dost vela) treba pilnikovat na kraji lebo niesu dost vyrezane a niektore dierky nejdu vytlacit (nevyrezane)

From:

<http://knowledge.lom.audio/> - **LOM knowledge base**

Permanent link:

http://knowledge.lom.audio/napady/elektrosluch_bugy

Last update: **2016/10/08 22:56**

