

- posunut prednu dierku na spodnej casti o 0.1mm

From:

<http://knowledge.lom.audio/> - **LOM knowledge base**

Permanent link:

http://knowledge.lom.audio/napady/elektrosluch_bugy?rev=1475750793

Last update: **2016/10/06 12:46**

