

- akryl o pol milimetra vyssi
- vzdialenosti noziciek na induktory
- pcb footprint induktorov je primaly
- strain-relief na baterku by mal mat viac kablíka

From:

<http://knowledge.lom.audio/> - **LOM knowledge base**

Permanent link:

http://knowledge.lom.audio/napady/elektrosluch_bugy?rev=1463765189

Last update: **2016/05/20 19:26**

