

- akryl o pol milimetra vyssi
- skontrolovat dlzku bocnic kvoli prednemu jacku - vyhnutie predneho
- vyska otvorov na cievky - zvyisit

From:

<http://knowledge.lom.audio/> - **LOM knowledge base**

Permanent link:

[http://knowledge.lom.audio/napady/elektrosluch\\_bugy?rev=1470143219](http://knowledge.lom.audio/napady/elektrosluch_bugy?rev=1470143219)

Last update: **2016/08/02 15:06**

