


Modul vyuzivajuci glitch, ktory 072 opampy robia, ked sa signal priblizuje k railu (iirc iba negativnemu).

obvod:

1. in
2. rozdelit na 2 halfwaves sposobom ktory nerobi voltage drop:



3. conditioning na -5v (resp +5v pre pozitivnu cast). bud ne570 limiter, alebo ne570compounder + ako poistka zener 5.1 limiter
4. gain na -12v (resp inverting gain pre pozitivnu cast na -12v) ←tu by mali vznikat glitche
5. attenuation (resp inverting attenuation) na -5v (resp +5v)
6. mix (+) a (-) halfwaves
7. out

From:

<http://knowledge.lom.audio/> - LOM knowledge base

Permanent link:

<http://knowledge.lom.audio/napady/glitch072?rev=1461597484>

Last update: **2016/04/25 17:18**

